



A STATE-OF-THE-ART REPORT ON BUILDING PATHOLOGY

CIB – W086
BUILDING PATHOLOGY

EDITED BY
VASCO PEIXOTO DE FREITAS





A STATE-OF-THE-ART REPORT ON BUILDING PATHOLOGY

**CIB – W086
BUILDING PATHOLOGY**

**EDITED BY
VASCO PEIXOTO DE FREITAS**

**CIB
A STATE-OF-THE-ART REPORT ON
BUILDING PATHOLOGY**

2013

COORDINATORS

Vasco Peixoto de Freitas	Portugal
Enrico de Angelis	Italy

AUTHORS

Ana Sofia Guimarães	Portugal
Albina Scioti	Italy
Antonella Guida	Italy
Antonello Pagliuca	Italy
Atila Koppány	Hungary
Bill Porteous	New Zealand
César Diaz	Spain
Clara Liaño	Spain
Eva Barreira	Portugal
Fabio Fatiguso	Italy
Filiberto Lembo	Italy
Francesco Marino	Italy
Giambatista de Tommasi	Italy
Ippolita Mecca	Italy
Inês Flores Colen	Portugal
Isabel Torres	Portugal
Ignacio Lombillo	Spain
Joan Lluís Zamora	Spain
Josifas Parasonis	Lithuania
Jorge de Brito	Portugal
J. Mendes da Silva	Portugal
Luis Villegas	Spain
Mariella de Fino	Italy
Miguel Vieira	Portugal
Pedro Lima Gaspar	Portugal
Romeu Vicente	Portugal
Sara Stingl de Freitas	Portugal
Sergio Croce	Italy
Vasco Peixoto de Freitas	Portugal
Vitor Córias	Portugal

CONTACT ADDRESS:

Vasco Peixoto de Freitas
 Building Physics Laboratory – LFC
 Porto University, Faculty of Engineering
 Rua Dr. Roberto Frias, 4200-465 Porto, Portugal
 Phone: +351 225 081 478
 E-mail: lfc-scc@fe.up.pt
 Web: <http://www.fe.up.pt/~lfc-scc>

EDITION:

CIB – International Council for Research and
 Innovation in Building and Construction
 FEUP – Porto University, Faculty of Engineering
 LFC – Building Physics Laboratory

COVER DESIGN:

Ana Stingl

ISBN – print:

ISBN – e-book:

LEGAL DEPOSIT:

All rights reserved. No part of this publication may be reproduced, stored in retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, recording and/or otherwise, without prior written permission of Publishers.



SUMMARY

The "State of the Art Report on Building Pathology" aims to be a concise document that binds a set of in-depth articles. A short introduction is provided in Chapter 1 to present the CIB W086 – Building Pathology Commission and to summarise its recent activities. Chapter 2 deals with Building Pathology and Costs, while Chapter 3 presents the Research Methodology.

Chapter 4 describes the Information Dissemination, and Chapter 5 is devoted to special Case Studies, where some practical examples are explained. Finally, Chapter 6 and 7 provide, respectively, the most important conclusions and the lists of all the reference documents that were taken into consideration to develop this document.



INDEX

CHAPTER 1– INTRODUCTION	13
1.1 THE CIB W086 – BUILDING PATHOLOGY COMMISSION	15
1.2 ACTIVITIES OF CIB W086 – BUILDING PATHOLOGY	15
1.2.1 SCOPE	15
1.2.2 MEMBERS	15
1.3 PUBLICATIONS	16
1.4 MEETINGS/CONFERENCES	16
 CHAPTER 2 – BUILDING PATHOLOGY AND COSTS	 17
2.1 THE IMPORTANCE OF BUILDING PATHOLOGY	19
2.1.1 INTRODUCTION	19
2.1.2 HOW USEFUL IS BUILDING PATHOLOGY?	19
2.1.2.1 SISTEMATIC SCIENTIFIC APPROACH	19
2.1.2.2 POSSIBLE DETECTION OF TRENDS AND PATTERNS	19
2.1.2.3 OBTAINING EMPIRICAL EVIDENCE	19
2.1.3 CONSEQUENCES OF APPLYING BUILDING PATHOLOGY?	20
2.1.3.1 AVOIDANCE OF SUPERFICIAL JUDGEMENT	20
2.1.3.2 BETTER DESIGN (AND SELECTION) TO AVOID FAILURES	20
2.1.3.3 DEVELOPMENT OF BETTER MATERIALS AND SPECIFICATIONS	20
2.1.4 CONCLUSIONS	20
2.1.5 REFERENCES	21
2.2 BUILDING PATHOLOGY RELATED COSTS	22
2.2.1 INTRODUCTION	22
2.2.2 BUILDING PATHOLOGY AND LIFE CYCLE COSTS	22
2.2.2.1 QUALITY COSTS	23
2.2.2.2 REHABILITATION COSTS	24
2.2.2.3 OTHER BUILDING PATHOLOGY RELATED COSTS	24
2.2.3 DATA ON BUILDING PATHOLOGY RELATED COSTS	25
2.2.3.1 DEFECT RELATED FAILURE COSTS	25
2.2.3.1.1 VISIBLE COSTS	25
2.2.3.1.2 HIDDEN COSTS	25
2.2.3.2 DEFECT RELATED RUNNING COSTS	25
2.2.3.2.1 EXTRA MAINTENANCE COSTS	25
2.2.3.2.2 EXTRA OPERATING COSTS	26
2.2.3.3 OTHER BUILDING PATHOLOGY RELATED COSTS	26
2.2.4 CONCLUSION AND RECOMMENDATION	26
2.2.5 REFERENCES	27
2.3 THE FRENCH, NORWEGIAN AND DANISH EXPERIENCE	28
2.3.1 INTRODUCTION	28
2.3.1.1 THE FRENCH EXPERIENCE	28
2.3.1.2 THE NORWEGIAN EXPERIENCE	28
2.3.1.3 THE DANISH EXPERIENCE	28
2.3.2 DEFECT DISTRIBUTION	29



2.3.2.1	BUILDING ELEMENTS AFFECTED	29
2.3.2.2	UNDERLYING CAUSES	30
2.3.3	BUILDING DEFECTS RELATED COSTS	32
2.3.4	CONCLUSION	33
2.3.5	REFERENCES	33
CHAPTER 3 – METHODOLOGY OF INVESTIGATION		35
3.1	FROM SINGULAR, ACCIDENTAL BUILDING PROBLEMS TO EARLY DEFECTS OF A CONGENITAL NATURE	37
3.1.1	INTRODUCTION	37
3.1.2	SINGULAR AND ACCIDENTAL PROBLEMS	37
3.1.3	GENERIC DEFECTS OF A CONGENITAL NATURE	38
3.1.4	AN UPDATE EXPERT METHOD	40
3.1.5	CONCLUSIONS	44
3.2	SOME CONSIDERATIONS ABOUT OBSERVATION METHODS, MEASUREMENTS AND TESTS FOR TECHNICAL INSPECTION OF BUILDINGS	45
3.2.1	RESOURCES FOR VISUALIZING HIDDEN AREAS	45
3.2.2	RESOURCES FOR VERIFYING ADHREENCE	45
3.2.3	RESOURCES FOR MEASURING THE SIZE OF FISSURES AND CRACKS	45
3.2.4	RESOURCES FOR MEASURING SAGGING OF FLOORS	46
3.2.5	RESOURCES TO QUANTIFY THE MISALIGNEMENT AND IRREGULARITY OF FAÇADES	46
3.2.6	RESOURCES TO CHECK THE CONDITION OF STRUCTURAL TIMBER ELEMENTS	46
3.2.7	RESOURCES TO CHECK THE CONDITION OF STRUCTURAL CONCRETE ELEMENTS	46
3.2.8	FINAL CONSIDERATIONS	47
3.2.9	REFERENCES	47
3.3	DIAGNOSTIC METHODOLOGICAL APPROACH: INNOVATIVE ASPECTS FOR MASONRY STRUCTURES	48
3.3.1	RESOURCES FOR VISUALIZING HIDDEN AREAS	48
3.3.2	THE DIAGNOSTIC PROCESS	48
3.3.2.1	METHODOLOGICAL APPROACHES	48
3.3.2.2	PROCESS PHASES	49
3.3.3	INNOVATIVE ASPECTS OF INTERACTION WITH THE DECISION MAKING PROCESS	50
3.3.3.1	GENERAL ISSUES	50
3.3.3.2	STRUCTURE OF KNOWLEDGE PROCESS	50
3.3.3.2.1	PRELIMINARY ANALYSIS AND PRE-DIAGNOSIS	51
3.3.3.2.2	FURTHER KNOWLEDGE	51
3.3.4	CONCLUSIONS	55
3.3.5	REFERENCES	55
3.4	TRADITIONAL AND INNOVATIVE TECHNIQUES FOR MONITORING HISTORICAL BUILDINGS	56
3.4.1	INTRODUCTION	56
3.4.2	MONITORING HISTORICAL STRUCTURES	56
3.4.3	TRADITIONAL METHODS AND TECHNIQUES	58
3.4.4	FROM MONITORING TO STRUCTURAL HEALTH CONTROL AND DAMAGE IDENTIFICATION	59
3.4.5	INNOVATIVE TECHNOLOGIES	60
3.4.6	REFERENCES	62



3.5	ASSESSMENT OF IN-USE PERFORMANCE PARAMETERS OF RENDERING FAÇADES	63
3.5.1	INTRODUCTION	63
3.5.2	RENDER CONDITION ASSESSMENT	63
3.5.2.1	REQUIRED AND SUPPLIED PERFORMANCE	63
3.5.3	CRITERIA AND TECHNIQUES	67
3.5.3.1	SURFACE CONDITION	67
3.5.3.2	MECHANICAL PERFORMANCE	67
3.5.3.3	PHYSICAL-CHEMICAL PERFORMANCE	68
3.5.3.4	INTERFACE COMPABILITY	68
3.5.4	RELIABILITY OF IN SITU ASSESSMENT	69
3.5.5	CONCLUSIONS	69
3.5.6	REFERENCES	70
3.6	QUALITY CONTROL IN DESTRUCTIVE SURVEYS	71
3.6.1	INTRODUCTION	71
3.6.2	SIGNIFICANCE OF THE DESTRUCTIVE QUALITY CONTROL METHODS	71
3.6.3	ASSESSMENT OF THE RESULTS OF THE DESTRUCTIVE QUALITY CONTROL METHODS	73
3.6.4	REFERENCES	75
3.7	SURVEY INFORMATION SHEETS	76
3.7.1	INTRODUCTION	76
3.8	DIAGNOSTIC SYSTEM FOR NON-DESTRUCTIVE SURVEYS OF BUILDING CONSTRUCTIONS	82
3.8.1	INTRODUCTION	82
3.8.2	DIAGNOSTIC SYSTEMS	82
3.8.3	EXPERIENCES OF FLAT ROOFS EXAMINATION	86
3.8.4	CONCLUSION	87
3.8.5	REFERENCES	87
3.9	NON (MINOR) DESTRUCTIVE METHODOLOGIES APPLIED TO THE STUDY AND DIAGNOSIS OF MASONRY STRUCTURES OF THE BUILT HERITAGE	88
3.9.1	INTRODUCTION	88
3.9.2	TECHNIQUES BASED IN MECHANICAL CRITERIA	88
3.9.3	TECHNIQUES APPLIED TO THE MORTARS CHARACTERIZATION	90
3.9.4	VISUAL INSPECTION TECHNIQUES	91
3.9.5	TECHNIQUES BASED IN ACOUSTIC WAVES PROPAGATION	91
3.9.6	TECHNIQUES BASED IN ELECTROMAGNETIC WAVES PROPAGATION	92
3.9.7	TOMOGRAPHIC TECHNIQUES	93
3.9.8	DYNAMIC CHARACTERIZATION	93
3.9.9	MONITORING TECHNIQUES	93
3.9.10	REFERENCES	93
3.10	APPLICATION OF INFRARED THERMOGRAPHY TO THE DIAGNOSIS OF FAÇADE RENDERING DETACHMENT	95
3.10.1	INTRODUCTION	95
3.10.2	PARAMETERS THAT AFFECT INFRARED THERMOGRAPHY	95
3.10.3	APPLICATION OF THERMOGRAPHY FOR DETACHMENT DETECTION	96
3.10.3.1	THE PHYSICS ASSOCIATED TO THE PATHOLOGY	96
3.10.3.2	LABORATORY MEASUREMENTS	97
3.10.3.2.1	PHYSICAL MODEL	97
3.10.3.2.2	TEST PROCEDURE	97
3.10.3.2.3	LABORATORY THERMOGRAMS	98
3.10.3.2.4	SUMMARY	99



3.10.3.3	<i>IN SITU</i> MEASUREMENTS	99
3.10.3.3.1	THE PATHOLOGY	99
3.10.3.3.2	PROCEDURE	99
3.10.3.3.3	<i>IN SITU</i> THERMOGRAMS	100
3.10.3.3.4	SUMMARY	100
3.10.3.4	COMPARISON OF NUMERICAL SIMULATION VS <i>IN SITU</i> RESULTS	100
3.10.4	CRITICAL ANALYSIS OF THE METHODOLOGY	101
3.10.5	CONCLUSIONS	101
3.10.6	ACKNOWLEDGMENTS	102
3.10.7	BIBLIOGRAPHY	102
CHAPTER 4	– INFORMATION DISSEMINATION	103
4.1	BUILDING PATHOLOGY CATALOGUES: DISSEMINATION OF KNOWLEDGE	105
4.1.1	INTRODUCTION	105
4.1.2	BUILDING PATHOLOGY CATALOGUES	106
4.1.2.1	EXISTING CATALOGUES IN PRINTED FORM	106
4.1.2.2	EXISTING CATALOGUES ON LINE	107
4.1.3	THE BUILDING PATHOLOGY STUDY GROUP – PATORREB	108
4.1.3.1	STRUCTURE OF THE WEBSITE	108
4.1.3.2	STRUCTURE OF THE PATHOLOGY REPORTS	109
4.1.3.2.1	IDENTIFICATION	109
4.1.3.2.2	DESCRIPTION	109
4.1.3.2.3	TEST/MEASUREMENTS	109
4.1.3.2.4	CAUSES	109
4.1.3.2.5	RECOMMENDATIONS	109
4.1.4	CONCLUSIONS	109
4.2	BUILDING PATHOLOGY DEFECT SHEETS: EXAMPLES	110
4.3	DAMAGE ATLAS OF CEMENT – RENDERED FAÇADES	113
4.3.1	INTRODUCTION	113
4.3.2	DAMAGE ATLAS FOR CEMENT– RENDERED FAÇADES	113
4.3.3	CLASSIFICATION OF DEFECTS IN CEMENT– RENDERED FAÇADES	113
4.3.3.1	STAINING	113
4.3.3.2	CRACKING	115
4.3.3.3	LOSS OF ADHERENCE	115
4.3.4	QUANTIFICATION OF OVERALL DETERIORATION OF FAÇADES	116
4.3.4.1	A CATALOGUE OF CASE STUDIES	117
4.3.5	CONCLUSION	118
4.3.6	REFERENCES	118
4.4	PATHOLOGY AND DEFECTS OF BUILDING FAÇADES AND ROOFS	120
4.4.1	INTRODUCTION	120
4.4.2	DEFECTS AND CONCEPTION OR DESIGN ERRORS	120
4.4.3	DEFECTS ON MASONRY WALLS	120
4.4.3.1	GENERAL SCOPE	120
4.4.3.2	NATURAL MOVEMENTS OF WALLS AND CRACKING	120
4.4.4	EXAMPLES	121
4.4.5	DEFECTS OF WINDOW SILLS	122
4.4.6	DEFECTS OF PITCHED ROOFS WITH CERAMIC TILING SLATES	123
4.4.7	DEFECTS ON FLAT ROOFS	125



4.4.8	FINAL NOTE	127
4.4.9	REFERENCES	128
4.5	WATERPROOFING MEMBRANE PATHOLOGY ANALYSIS AS A MEANS OF INNOVATION: THE CASE OF EUROPE	129
4.5.1	INTRODUCTION	129
4.5.2	PATHOLOGIES AND BITUMEN BASED MEMBRANE INNOVATION	130
4.5.3	PATHOLOGIES AND SYNTHETIC MEMBRANES INNOVATION	137
4.5.4	CONCLUSIONS	141
4.5.5	REFERENCES	142
4.6	RISING DAMP PATHOLOGY DIAGNOSIS AND TREATMENT	143
4.6.1	THE PROBLEM	143
4.6.2	TREATMENT METHODS	143
4.6.2.1	INSTALLATION OF MOISTURE BARRIER	143
4.6.2.2	DISGUIISING ANOMALIES	144
4.6.2.3	ELECTROOSMOSIS	145
4.6.2.4	KNAPPEN TUBES	145
4.6.2.5	WALL BASE VENTILATION	145
4.6.2.6	ANDANTAGES AND DRAWBACKS OF THE TREATMENT METHODS	145
4.6.3	TESTING WALL BASE VENTILATION TECHNOLOGY	146
4.6.3.1	EXPERIMENTAL STUDY	146
4.6.3.1.1	PHYSICAL MODEL	146
4.6.3.1.2	RESULTS	147
4.6.3.2	NUMERICAL SIMULATION	147
4.6.3.3	IMPLEMENTING THE SYSTEM	147
4.6.3.3.1	SYSTEM INSTALLED	147
4.6.3.3.2	FUNCTIONING CRITERIA: PREVENTING CONDENSATIONS	148
4.6.4	CONCLUSIONS	148
4.6.5	REFERENCES	149
4.7	RELATIONS AMONG PATHOLOGIES, BUILDING TECHNOLOGIES AND BUILDING TYPOLOGIES	150
4.7.1	INTRODUCTION	150
4.7.2	THE E.P.E.R IN THE PROVINCE OF POTENZA	150
4.7.3	RELATIONSHIPS BETWEEN TECHNOLOGICAL SOLUTIONS AND RECURRING PATHOLOGIES – FREQUENT PROJECTUAL AND BUILDING MISTAKES	153
4.7.4	CONCLUSIONS	155
CHAPTER 5	– CASE STUDIES	157
5.1	COMPARATIVE DIAGNOSTIC AS AN INSTRUMENT FOR INTERVENTION'S DURABILITY	159
5.1.1	INTRODUCTION	159
5.1.2	THE "SUITABLE" INTERVENTION CHOICE	159
5.1.3	THE CASE STUDY: MATHERA'S CATHEDRAL	160
5.1.4	CONCLUSION	161
5.1.5	REFERENCES	162
5.2	CAUSES: PROCESSES WHERE THERE IS LACK OF QUALITY CONTROL, ERRORS IN PLANNING OR EXECUTING	163
5.2.1	INTRODUCTION	163



5.2.2	SURVEY FIELD	163
5.2.3	RELATION BETWEEN PROCESS QUALITY AND PRODUCT QUALITY	164
5.2.3.1	ROMA, CORVIALE	164
5.2.3.2	POZZUOLI, MONTERUSCIELLO	165
5.2.4	CONCLUSIONS	166
5.2.5	REFERENCES	167
5.3	MIXED STRUCTURE BUILDINGS OF THE EARLY XX CENTURY: PATHOLOGIES AND CAUSES	168
5.3.1	INTRODUCTION	168
5.3.2	SLABS	168
5.3.3	STAIRCASES	170
5.3.4	CONCLUSIONS	176
5.3.5	REFERENCES	176
5.4	THE DURABILITY OF BUILT HERITAGE THROUGH TESTS AND EXPERIMENTATIONS ON SITE	177
5.4.1	INTRODUCTION	177
5.4.2	OPERATIVE PLANNING METHODOLOGY	177
5.4.3	CASE STUDY: THE SASSI OF MATERA	178
5.4.4	RECOVERY INTERVENTIONS DURABILITY IN THE SASSI	178
5.4.5	TECHNOLOGICAL TESTS	179
5.4.6	DAMAGE EVOLUTION OVER TIME IN ANCIENT BUILDING STRUCTURES	180
5.4.6.1	STRUCTURAL TESTS	180
5.4.6.2	PENETRATION METER TEST	181
5.4.7	CONCLUSIONS	182
5.4.8	REFERENCES	182
CHAPTER 6	– CONCLUSION	183
CHAPTER 7	– BIBLIOGRAPHY	187